

Connections

1. Load Cell connections : (DB-09 Female)

Pin no. 1,2 3 4,5 6,7 8,9
 EXC+ GND EXC- SIG+ SIG-

2. RS232C connections : (DB-09 male)

Pin no. 2 5 others
 TXD GND NC

Error message

Symptom	Cause	Solution
	Over load :	
	* Weighing range exceed	> Unload scale or reduce preload
	Under load :	
	* Weighing pan not in place	> Ensure the weighing pan is correctly installed and surrounding parts are not touching
	* Weighing range zero below	> Set scale to zero
	* Contact between weighing	> Apply pre-load
	Zeroing not possible :	
	* Zeroing outside the zero setting range	> Ensure that zeroing is performed in the admissible range (20% of Cap.)

PS-30 Weighing Indicator



Operation Manual

You have purchased a quality precision weighing instrument that requires handling with care. Read entire contents of this **Operation Manual** prior to operating your new instrument.

Disclaimer Notice

Calibrate your instrument using reference weights of the appropriate tolerance (class). An instrument can be no more accurate than the standard to which it has been compared. For assistance in the selection of reference weights, please contact the factory.

Caution: Changes or modifications not expressly approved by the manufacturer could void the user's authority to operate this equipment.

Introduction

Thank you for choosing one of our instruments. Your instrument is designed and manufactured to the most rigorous standards in order to give you years of service. First, check the contents of the shipping carton. You should find the following :

*** Manual * Instrument * AC Adapter**

Next, follow the instructions for installing your instrument.

Now you are ready to begin using your instrument. To take advantage of its many features, carefully read your operating manual.

It contains step-by-step procedures, examples, and other vital information.

Warning: Use of this product in a manner not specified by the manufacturer may impair any safety protection provided by the equipment!

Calibration

In step of **Weight calibrate**, press \star key and Display shows **Offset value to be 5000 ~ 50000**
If it's not in this range **Sw1** to be adjust.

22.222

1. Press $-0-$ key to zero display.

0

2. Put the **calibrating weight** on the platform.

12.2222

Span value to be 50000 ~ 150000 at full capacity

The lower calibrating weights are available.
such as 1/4, 1/3 or 1/2 capacity.

3. The calibrating number can be changeable by the key \leftarrow , \wedge
Press the \star key, the **SPAN** setting to be done.

2.2222
5.-----

4. The calibrating number can be changeable by the key \leftarrow , \wedge
Calibrating number = FULL CAPACITY + OVER RANGE

2.2222

The OVER RANGE can be 9d or 5% of full capacity.

Press the \star key, the **CAPACITY** setting to be done.

[-.-----

5. After finish the weight calibration, make the **Jp3 switch ON**.
Now you are ready to weigh.

RS232C Specifications

1. **Baud rate** : 2400/9600 selectable

Parity : none

Data bit : 8

Stop bit : 1


2. **Format**

Number : 1 2 3 4 5 6 7 8 9 10 11 12 13

Caractors : SP/- X X X X X X X SP k/l g/b CR LF

Calibration

Please have the jumper *Jp3 switch OFF*, before you start to calibrate weight.

Press and hold any key and then press , and display shows



Press  key goes to **weight calibrate sequence**.

Press  key for **quick scrolling check**

Press  key for **parameter selecting** and

Press  key for **setting and goes to next step**. The programme sequence as follows:

A. Units



lb



kg



kg/lb

B. Grad size

























C. Auto zero tracking



Off



0.5 divisions




1 division




2 divisions

D. Zero range




Re-zero range 100% of Cap.



Re-zero range 2% of Cap.


E. Weight calibrate





Function keys



- Turns instrument **On**.
- The  to be a print out key.



Turns instrument **Off**.



Captures a new center of zero.




Reduce gross weight on pan as tare weight.




Units select kg / lb.



The  to be a function of moves the flashing cursor digit to the left.




The  to be a function of increases the flashing cursor by one digit.




Setting.

Operation

A. Getting Started


1. Ensure nothing is on the platform and turn the instrument ON.
2. Turn the instrument ON by pressing the  key.
3. The display will run through a self diagnostic digit check *B.B.B.B.B.B.* and will then indicate zero.
4. **Allow the instrument to warm-up for 30 minutes.**

B. Weighing units


1. Should you wish to change the weighing units press the  key..
2. The small arrow in the display will alternately between **kg** and **lb**.
3. Switch ON and OFF will not affect the programmed units.

C. Taring (zeroing)


All models have taring (zeroing) capabilities up to their total weight capacity.
To weigh a sample in its container with the display showing the weight of the sample use the following ZERO (tare) procedure.

1. Place sample container on pan and then press the  key and indicator will lights at **NET**.
2. Now place sample in its container.
3. When the scale is stable, the display shows the weight of the sample.

D. Battery charge

Build in 6V Rechargeable-battery.
Battery operating limited at 5.5V and indicator will lights at  .
In this time the instrument should be charging.

E. Motion detect

When weighing unstable, the indicator will lights at  .




















Programme








Press and hold any key and then press , and display shows 

Press  key goes to **programme sequence**.


Press  key for **parameter selecting** and

Press  key for **setting and goes to next step**. The programme sequence as follows:

A. Auto power off		None
		5 minutes after
		10 minutes after
		20 minutes after
		30 minutes after
B. Backlit		None
		Active
		Auto lighting while loading
C. Zero setting		Initial zero auto
		Initial zero memorized
D. RS 232 output		None
		Manual
		Auto
		Continuously
E. Baud rate		Baud rate 2400
		Baud rate 9600
F. Weighing lock		None
		Enable
		Lock range adjustable

In step , the display will shows lock range 
The range can be changeable by the key , 
Press the  key, the lock range setting to be done. 


For example:

 It means the lock range is +/- 3
If the movement is between 97 and 103, then the scale will lock on,
and display the average of 100 and sounds beep.