

Weighing Indicators

Features:

- Large LCD with Backlight
- Key Calibration
- Rechargeable Battery Inside
- Auto Shut-off
- Kg / lb Conversion
- Weighing lock function (PS 30, PS PLUS)
- Selectable Capacity
- ID Number / Date setting (PS PLUS)
- Programmable accuracy, decimal point (PS 30, PS PLUS)
- Simple Counting Function



Options:

- RS 232 Interface
- Wall Mounting
- Rotate Structure
- Junction Box
- Dust Cover



Specifications:

Model	PS Series Indicator
Display Resolution	1 / 10,000 (III)
Internal Resolution	1 / 30,000
Load Cell	Drive up to max. 4 load cells (350ohm)
Full Scale Input Signal	10mV
L/C Excitation Voltage	DC 5V
Operation Environment	0°C ~ 40°C, RH less than 85%
Power	AC Adaptor 9V / Lead-Acid Rechargeable Battery 6V
Net Weight	1.6Kg

Weighing Indicators

